

FIELD INSPECTION

TIEED INGI ESTIGIA			
Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Thursday, August 16, 2018	Project Contact:	Brian Clauto
Spread: Locations inspect near: MP 263 ST#13888- 13893 MP 254 ST#13421- 13424, ST #13439	Spread I	Weather (Wet/Dry/Rain):	Dry
STAGE OF CONSTRUCTION: (Check all that apply)			
Clearing	Rough Grading	Trench Excavation	Pipe Assembly, Testing & Installation
Backfilling and Grade	e Restoration	& Stabilization	Other:
Yes No N/A Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?			
Are all control measures properly maintained in effective operating 2 condition in accordance with good engineering practices and, where applicable, manufacturer specifications?			
3 Areas of offsite sediment deposition were observed? □ □ □			
Comments: Area 1 - Spread I, near MP 263 ST#13888 slope drain system observed not built per DEQ site specific approval. Recommended Corrective Action: Install slope drain per DEQ site-specific approval. .			
Deadline:Within 24hr notification			
The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project. Inspector Signature:			



FIELD INSPECTION PHOTO LOG

Project Name: <u>Mountain Valley Pipeline</u> Date:Thursday, August 16, 2018

Fig. 1 Near station 13888+00 observed slope drain system not built per approval



Fig. 2
Near station 13888+00 observed slope drain system not built per approval



Fig. 3 Near station 13421+99, restoration in progress



Fig. 4
Observed matted slope installed above designated stream S-IJ 4